

L) Remarks

Engine 1 was originally dispatched to an Alarm Activation at this address. On arrival Engine 1 had a report of a broken water pipe on the 19th floor. Engine 1 requested an additional Ladder at this time to assist with probable water evacuation. While checking the elevators for availability Engine 1 observed moderate smoke in the elevator shaft and upgraded the alarm to a Highrise Alarm per SOG. On arrival all tactical assignments were filled per SOG as follows: Ladder 3 Fire Attack 1, Engine 1 Fire Attack 2, Engine 2 Fire Attack 3, Engine 4 Water Supply, Engine 3 Lobby Control, Engine 6 Fire Control Room, Quint 17 Recon, Ladder 15 Resource, and Battalion 6 Incident Command.

Initial size up report indicated the alarm panel displaying a water flow alarm on the 30th, 19th, 16th, 14th and 1st floors. No FIRE alarms were displayed on the panel. The smoke in the elevator shaft had dissipated but water was observed running down the walls of all shafts. All four elevators were inoperable with the elevators on the SW and NE corners recalled to the 1st floor and the SE elevator stopped on the 10th floor, and a report of occupants stuck in the service elevator between the 5th and 6th floor.

Initial strategy was to verify that a water pipe had broken on the 19th floor, find out why we had a water flow alarm on the 30th floor, removal of the reported occupants in the service elevator, make sure the smoke in the elevator shaft was caused by a shorted elevator motor, and to check the welfare of an occupant reported on the 24th floor.

Fire Attack 1 proceeded to the 19th floor via the north stairwell and verified that there was a broken water pipe on that floor which caused a fluctuation in the system and triggered the other water flow alarms. Engine 1 checked status on the elevator motor. Engine 2 removed 2 occupants out of the stalled elevator, and Quint 17 met with and checked status of the occupant on the 24th floor.

Alarm was reduced to Ladder 3, Ladder 15, and Engine 1. All 3 units assisted general contractors with water removal until released.

Water damage assessment was as follows: 19th floor Units 1901, 1902, 1903, 1904, 1905, 1906, and 1907 had complete floor damage throughout entire units. 1909 had 50% damage throughout. 1908, 1910, and 1911 were undamaged. 75% of the hallway carpet had water damage. 70% of the ceiling had fallen down or had some water damage. 18th floor had significant damage throughout the entire floor. 14th through the 17th floors had sporadic damage throughout the floor. 9th through the 13th floors had minor damage mainly from the telephone cable rooms and the center hallway and elevator lobby areas. Initial damage was estimated at \$750,000. Sprinkler company was on scene, elevator company was on scene, water restoration company was on scene, and the building was released back to the general contractors. NOI.

Apparatus Information

NFIRS -9 APPARATUS

<u>Apparatus</u>	<u>Staffing</u>	<u>Dispatch Time/Date</u>	<u>Responding Time/Date</u>	<u>Onscene Time/Date</u>	<u>In Service Time/Date</u>	<u>Use</u>
BATTALION 4	43513073	09/11/2008 14:35:16	09/11/2008 14:37:52	09/11/2008 14:45:10		43513073
BATTALION 6	43513059	09/11/2008 14:35:16	09/11/2008 14:36:07	09/11/2008 14:41:44		43513059
DC NOTIFY	43513103	09/11/2008 14:35:16				43513103
ENGINE 01	43512699	09/11/2008 14:21:34	09/11/2008 14:22:59	09/11/2008 14:26:18		43512699
ENGINE 02	43513318	09/11/2008 14:36:46	09/11/2008 14:36:46	09/11/2008 14:38:27		43513318
ENGINE 03	43513016	09/11/2008 14:35:16	09/11/2008 14:38:05	09/11/2008 14:44:34		43513016
ENGINE 04	43512986	09/11/2008 14:35:16	09/11/2008 14:38:59	09/11/2008 14:39:01		43512986
ENGINE 06	43512993	09/11/2008 14:35:16	09/11/2008 14:37:16	09/11/2008 14:41:20		43512993
LADDER 03	43512776	09/11/2008 14:28:36	09/11/2008 14:30:17	09/11/2008 14:37:35		43512776
LADDER 15	43512972	09/11/2008 14:35:16	09/11/2008 14:37:06	09/11/2008 14:45:32		43512972
QUINT17	43512965	09/11/2008 14:35:16	09/11/2008 14:37:41	09/11/2008 14:44:33		43512965
RESCUE 20	43513030	09/11/2008 14:35:16	09/11/2008 14:36:32	09/11/2008 14:46:07		43513030
SAFE01	43513268	09/11/2008 14:37:00	09/11/2008 14:37:00	09/11/2008 14:46:23		43513268